# Oil Field Environmental Incident Summary

**Responsible Party:** CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: POLK FEDERAL 3-33H1

Field Name: BANKS Well File #: 27343

Date Incident:2/18/2015Time Incident:10:00Facility ID Number:County:MCKENZIETwp: 153Rng: 98Sec: 33Qtr:

Location Description:

Submitted By: Justin Collins Received By:

Contact Person: Justin Collins

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

**Brine** 

Other 5 Barrels 5 Barrels 5 barrels

**Description of Other Released Contaminant:** 

Slick-water

Inspected: Written Report Received: 10/3/2016 Clean Up Concluded: 2/20/2015

Risk Evaluation:

None

Areal Extent:

## Potential Environmental Impacts:

Well site soil

### Action Taken or Planned:

Replaced piping. Sucked up fluid.

Wastes Disposal Location: N/A

Agencies Involved:

## **Updates**

Date: 2/20/2015 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

Release, due to an on-location valve/piping leak, remained on location according to the report. NDIC retains oversight.